

VEHICLE

MAKE / MODEL	Kia K5	YEAR	—	PLATE	FF38230 — Dubai
CUSTOMER	Mr. Bassil Al HALKI	MILEAGE	— km	VIN	5XXG64J24RG239857

OUR DIAGNOSIS

يوجد اعطال في الإسلام الكهربائيه للكشافات الالمانية (بسبب ان الكشافات تجاري وليست اصلي) نظام الان اسست لا يعمل بكفاءة نظرا لتغيير المرباط التجاري يوجد كشاف خلفي يمين به شرخ بسيط تحتاج تغيير طرف زراع التوجيه الايمن الكشاف الخلفي اليسار به اجزاء لا تعمل السيارة لا يعمل السينسور بارك الامامي وتحتاج سينسور خلفي المخفي يحتاج الي تغيير تحتاج تغيير زيت وفلتر و تغيير اولسيهات كب الفلتر تحتاج تغيير البوجيهات تغيير فلتر تحتاج تغيير تيرت وترصيص و طبط الإلتزام

REPAIR QUOTE (AED)

ITEM	TYPE	QTY	AMOUNT (AED)
TIENT	New part	1	550
Spark plug	New part	1	220
TIE ROD END RH	New part	1	100
AC Filter	New part	1	70
PARKING SENSOR WITH ANDROID OPTION	New part	1	700
K 235/45 R18	New part	1	1800
Parts total (chosen items)			3440
CHANGING ALL PARTS	Labour	—	370
Labour total			370
TOTAL			3810

YOUR OPTIONS — FULL JOB (AED)

IF YOU CHOOSE	PARTS	LABOUR	TOTAL
New genuine أورجيناال جديد	3440	370	3810

Each line is the whole job with every part at that grade. You may mix grades — tick the option you want next to each part above. * some parts were only available at another grade; their price is included as found.

To approve this quote: simply reply **APPROVE** on WhatsApp **+971 54 582 6226** and we will start the work right away.

Used parts are tested before installation · Repairs covered by our 30-day workmanship warranty · Prices include the listed items only — any additional fault found will be quoted separately for your approval.

