

VEHICLE

MAKE / MODEL	Mercedes GLK	YEAR	—	PLATE	18139 — Dubai
CUSTOMER	Me george	MILEAGE	131000 km	VIN	WDCGG8JB8EG180684

REPORTED COMPLAINT

2 rear suspensions Battery Wheel Bearin

OUR DIAGNOSIS

Diagnosis in progress — will be shared shortly.

REPAIR QUOTE (AED)

ITEM	TYPE	QTY	AMOUNT (AED)
Change wheel bearings both of them	Labour	—	400
Change suspensions both of them	Labour	—	300
Change battery and reset computer	Labour	—	100
Labour total			800
TOTAL			800

To approve this quote: simply reply **APPROVE** on WhatsApp **+971 54 582 6226** and we will start the work right away.

Used parts are tested before installation · Repairs covered by our 30-day workmanship warranty · Prices include the listed items only — any additional fault found will be quoted separately for your approval.