

VEHICLE

MAKE / MODEL	Mercedes G class	YEAR	—	PLATE	O3110 — Dubai
CUSTOMER	Ahmed	MILEAGE	— km	VIN	—

REPORTED COMPLAINT

Problem in suspension

OUR DIAGNOSIS

تم تغيير المساعد الخلفي و ليزر الدرامات و جهاز الشاشة و اصلاح عزم السيارة

REPAIR QUOTE (AED)

ITEM	TYPE	QTY	AMOUNT (AED)
ميساعد خلفي	Customer-supplied	1	—
ليزر للدرامات	New part	1	800
جهاز الشاشة الامامية	Customer-supplied	1	—
SPARK PLUG	New part	1	600
Parts total (chosen items)			1400
LABOR CHARGE	Labour	—	3400
Labour total			3400
TOTAL			4800

YOUR OPTIONS — FULL JOB (AED)

IF YOU CHOOSE	PARTS	LABOUR	TOTAL
New genuine * جديد أورجيناال	1400	3400	4800

Each line is the whole job with every part at that grade. You may mix grades — tick the option you want next to each part above. * some parts were only available at another grade; their price is included as found.

To approve this quote: simply reply **APPROVE** on WhatsApp **+971 54 582 6226** and we will start the work right away.

Used parts are tested before installation · Repairs covered by our 30-day workmanship warranty · Prices include the listed items only — any additional fault found will be quoted separately for your approval.

