

VEHICLE

MAKE / MODEL	Audi A5	YEAR	—	PLATE	H66571 — Dubai
CUSTOMER	—	MILEAGE	— km	VIN	WAUACBFH2FN006A41

REPORTED COMPLAINT

تسريب هواء

OUR DIAGNOSIS

1:تسريب هواء و زيت المطلوب 1 Steering rack boots replacement 2:Lower control arms replacement 3:Spark plugs replacement 4:Fuel leak repair 5:Air filter replacement 6:Engine oil seal replacement 7:Engine cooling system flush 8:Front and rear brake pads replacement 9:Front and rear brake discs replacement 10:Fuel injectors cleaning 11:Shock Absorbers / Struts 12:Fuel Rail Pressure Sensor 13:Intercooler Pipe

REPAIR QUOTE (AED)

ITEM	TYPE	QTY	AMOUNT (AED)
Turbo pipe	New part	1	—
Oil engine 5L	Used part	1	—
Filter engine	New part	1	—
Change oil and filter	Labour	—	150
Cover engine and oil pan	Labour	—	500
Pipe turbo	Labour	—	200
Labour total			850
TOTAL			850

To approve this quote: simply reply **APPROVE** on WhatsApp **+971 54 582 6226** and we will start the work right away.

Used parts are tested before installation · Repairs covered by our 30-day workmanship warranty · Prices include the listed items only — any additional fault found will be quoted separately for your approval.