

VEHICLE

MAKE / MODEL	Audi A5	YEAR	—	COLOR	White
PLATE	H66571 — Dubai	MILEAGE IN	— km	VIN	WAUACBFH2FN006A41

CUSTOMER

NAME	—	PHONE	—	JOB CARD	JC-9805
------	---	-------	---	----------	---------

JOB SUMMARY

STATUS	Delivered	CHECKED IN	20/07 14:14	DELIVERED	16/08 16:45
DAYS IN SHOP	27.1	INVOICE (AED)	1399	ODOO INVOICE	287
COMPLAINT	تسريب هواء				
DIAGNOSIS	1:تسريب هواء و زيت المطلوب 2:Steering rack boots replacement 3:Lower control arms replacement 4:Spark plugs replacement 5:Fuel leak repair 6:Air filter replacement 7:Engine oil seal replacement 8:Engine cooling system flush 9:Front and rear brake pads replacement 10:Front and rear brake discs replacement 11:Fuel injectors cleaning 12:Shock Absorbers / Struts 13:Fuel Rail Pressure Sensor 13:Intercooler Pipe				

PARTS USED

PART	TYPE	QTY	AMOUNT (AED)
Turbo pipe	New	1	—
Oil engine 5L	Used	1	—
Filter engine	New	1	—
Change oil and filter	Labour	—	150
Cover engine and oil pan	Labour	—	500
Pipe turbo	Labour	—	200
Labour total			850
Total (parts + labour)			850

WORK TIMELINE

DATE / TIME	EVENT	BY
20/07 14:14	Checked in — Reception	Yes
20/07 14:18	Note: Changed engine oil pan, cover engine	
20/07 19:12	Note: Diagnosis: تسريب هواء و زيت	
20/07 19:12	Moved to Awaiting Approval	
21/07 08:09	Note: تم تركيب مساعد الكابوت	
21/07 11:39	Moved to Sourcing Parts	
21/07 19:39	Moved to In Repair	Yes

21/07 19:40	Note: Part added: Turbo pipe x1 (N)	Yes
21/07 19:40	Note: Part added: Oil engine x1 (N)	Yes
21/07 19:41	Note: Part removed: Oil engine	
21/07 19:41	Note: Part added: Oil engine 5L x1 (U)	Yes
21/07 19:41	Note: Part added: Filter engine x1 (N)	Yes
21/07 19:43	Note: Labour set: 850 AED	Yes
22/07 09:32	Labour 850 AED itemized (migration)	Claude
22/07 13:18	Note: Diagnosis: 1 تسريب هواء و زيت المطلوب 1:Steering rack boots replacement 2:Lower control arms replacement 3:Spark plugs replacement 4:Fuel leak repair 5:Air filter replacement 6:Engine oil seal replacement 7:Engine cooling system flush 8:Front and rear brake pads replacement 9:Front and rear brake discs replacement 10:Fuel injectors cleaning 11:Shock Absorbers / Struts 12:Fuel Rail Pressure Sensor 13:Intercooler Pipe	Yes
22/07 13:18	Moved to Awaiting Approval	Yes
22/07 18:41	Note: Labour removed: Labour	
22/07 18:41	Note: Labour added: Pipe terbo — 300 AED	Yes
22/07 18:42	Note: Labour removed: Pipe terbo	
22/07 18:42	Note: Labour added: Pipe turbo — 300 AED	Yes
22/07 18:42	Note: Labour added: Change oil and filter — 150 AED	Yes
22/07 18:49	Moved to Wash	Yes
23/07 14:25	Moved to Delivered	Yes
25/07 17:30	Note: Labour added: Cover engine and oil pan — 500 AED	Yes
25/07 17:30	Note: Labour added: Pipe turbo — 200 AED	Yes
25/07 17:30	Note: Labour removed: Pipe turbo	
16/08 16:45	Moved to Delivered	Youssef