

VEHICLE

MAKE / MODEL	Infinity QX70s	YEAR	—	COLOR	Gray
PLATE	36185 — Dubai	MILEAGE IN	— km	VIN	—

CUSTOMER

NAME	—	PHONE	—	JOB CARD	JC-9815
------	---	-------	---	----------	---------

JOB SUMMARY

STATUS	Delivered	CHECKED IN	20/07 20:29	DELIVERED	25/07 15:50
DAYS IN SHOP	4.8	INVOICE (AED)	3350	ODOO INVOICE	286
COMPLAINT	سخونة				
DIAGNOSIS	مطلوب تغيير water pump, thermostat and Radiator cap				

PARTS USED

PART	TYPE	QTY	AMOUNT (AED)
Radiator cap	Used	1	—
Water pump	New	1	—
thermostat	Used	1	—
Cleaning Throttle Body gate	Labour	—	150
Change thermostat	Labour	—	250
Change water pump	Labour	—	350
Change Radiator cup	Labour	—	—
Change battery and reset computer	Labour	—	100
Change spark plug	Labour	—	150
Change rubber gaskets	Labour	—	250
Labour total			1250
Total (parts + labour)			1250

WORK TIMELINE

DATE / TIME	EVENT	BY
20/07 20:29	Checked in — Reception	Yes
20/07 20:30	Moved to Diagnosis	
22/07 12:46	Note: Diagnosis: مطلوب تغيير water pump, thermostat and Radiator cap	Yes
22/07 12:46	Note: Diagnosis: مطلوب تغيير water pump, thermostat and Radiator cap	Yes
22/07 12:46	Moved to Awaiting Approval	Yes

22/07 12:46	Note: Part added: Radiator cap x1 (U)	Yes
22/07 12:47	Note: Part added: Water pump x1 (N)	Yes
22/07 12:47	Note: Part added: thermostat x1 (U)	Yes
23/07 11:13	Note: Diagnosis: مطلوب تغير water pump, thermostat and Radiator cap	Yes
23/07 19:00	Moved to Sourcing Parts	
24/07 11:06	Moved to In Repair	
24/07 13:00	Note: Labour added: Cleaning Throttle Body gate — 150 AED	Yes
24/07 13:03	Note: Labour added: Change water pump — 400 AED	Yes
24/07 13:04	Note: Labour added: Change thermostat — 250 AED	Yes
24/07 13:04	Note: Labour added: Change water pump — 350 AED	Yes
24/07 13:04	Note: Labour removed: Change water pump	
24/07 13:05	Note: Labour added: Change Radiator cup — 0 AED	Yes
24/07 13:07	Note: Labour added: Change spark plug — 200 AED	Yes
24/07 13:08	Note: Labour added: Change battery and reset computer — 100 AED	Yes
25/07 09:10	Note: Labour added: Change spark plug — 150 AED	Yes
25/07 09:11	Note: Labour removed: Change spark plug	
25/07 09:12	Note: Labour added: Change rubber gaskets — 180 AED	Yes
25/07 09:44	Note: Labour added: Change rubber gaskets — 250 AED	Yes
25/07 09:44	Note: Labour removed: Change rubber gaskets	
25/07 13:24	Moved to Ready for Pickup	Yes
25/07 15:50	Moved to Ready for Pickup	
25/07 15:50	Moved to Ready for Pickup	
25/07 15:50	Moved to Delivered	