

VEHICLE

MAKE / MODEL	Mercedes A250	YEAR	—	PLATE	D90971 — Dubai
CUSTOMER	Ms.shima	MILEAGE	— km	VIN	WDDBF4EB2FJ325976

REPORTED COMPLAINT

Turbo not working

OUR DIAGNOSIS

الكشف لم ينتهي و العميل قال هجيب السيارة غدا

REPAIR QUOTE (AED)

ITEM	TYPE	QTY	AMOUNT (AED)
Parts	New part	1	4725
Parts total (chosen items)			4725
Engine repair	Labour	—	1175
Labour total			1175
TOTAL			5900

YOUR OPTIONS — FULL JOB (AED)

IF YOU CHOOSE	PARTS	LABOUR	TOTAL
New genuine جديد أورجيناال	4725	1175	5900

Each line is the whole job with every part at that grade. You may mix grades — tick the option you want next to each part above. * some parts were only available at another grade; their price is included as found.

To approve this quote: simply reply **APPROVE** on WhatsApp **+971 54 582 6226** and we will start the work right away.
Used parts are tested before installation · Repairs covered by our 30-day workmanship warranty · Prices include the listed items only — any additional fault found will be quoted separately for your approval.