

VEHICLE

MAKE / MODEL	Mercedes C200	YEAR	—	PLATE	O95376 — Dubai
CUSTOMER	Engineer adel	MILEAGE	160128 km	VIN	Wddwf8ab8kr479292

REPORTED COMPLAINT

خلط مياه وزيت

OUR DIAGNOSIS

Diagnosis in progress — will be shared shortly.

REPAIR QUOTE (AED)

ITEM	TYPE	QTY	AMOUNT (AED)
Oil Cooler	New part	1	740
Oil Cooler Seal	New part	1	35
Coolant Red	New part	1	110
RECOVERY	New part	1	100
Parts total (chosen items)			985
CLEANING WATER CIRCULE	Labour	—	500
Labour total			500
TOTAL			1485

YOUR OPTIONS — FULL JOB (AED)

IF YOU CHOOSE	PARTS	LABOUR	TOTAL
New genuine جديد أوريجنال	985	500	1485

Each line is the whole job with every part at that grade. You may mix grades — tick the option you want next to each part above. * some parts were only available at another grade; their price is included as found.

To approve this quote: simply reply **APPROVE** on WhatsApp **+971 54 582 6226** and we will start the work right away.

Used parts are tested before installation · Repairs covered by our 30-day workmanship warranty · Prices include the listed items only — any additional fault found will be quoted separately for your approval.

