

VEHICLE

MAKE / MODEL	Bentley .	YEAR	—	PLATE	U18995 — Dubai
CUSTOMER	Engineer adel	MILEAGE	99695 km	VIN	SCBBE53W5DC078997

REPORTED COMPLAINT

Electric issue

OUR DIAGNOSIS

Both head light and ac gas

REPAIR QUOTE (AED)

ITEM	TYPE	QTY	AMOUNT (AED)
Xenon bulb rh and left	New part	1	220
Parts total (chosen items)			220
Ac charge	Labour	—	200
Fix head light	Labour	—	150
Fix camera	Labour	—	100
Rims paint	Labour	—	500
Remove and install the interior door panels	Labour	—	300
Labour total			1250
TOTAL			1470

YOUR OPTIONS — FULL JOB (AED)

IF YOU CHOOSE	PARTS	LABOUR	TOTAL
New genuine جديد أورجینال	220	1250	1470

Each line is the whole job with every part at that grade. You may mix grades — tick the option you want next to each part above. * some parts were only available at another grade; their price is included as found.

To approve this quote: simply reply **APPROVE** on WhatsApp +971 54 582 6226 and we will start the work right away.
Used parts are tested before installation · Repairs covered by our 30-day workmanship warranty · Prices include the listed items only — any additional fault found will be quoted separately for your approval.

