

VEHICLE

MAKE / MODEL	Geely Emgrand	YEAR	—	PLATE	K84339 — Dubai
CUSTOMER	Valtinu	MILEAGE	— km	VIN	LB3F31S24RG016816

REPORTED COMPLAINT

mirror broken

OUR DIAGNOSIS

Left Mirror broken in small part need to Repair

REPAIR QUOTE (AED)

ITEM	TYPE	QTY	AMOUNT (AED)
Fixed left Mirror	Labour	—	150
Labour total			150
TOTAL			150

To approve this quote: simply reply **APPROVE** on WhatsApp **+971 54 582 6226** and we will start the work right away.

Used parts are tested before installation · Repairs covered by our 30-day workmanship warranty · Prices include the listed items only — any additional fault found will be quoted separately for your approval.