

VEHICLE

MAKE / MODEL	Ford Focus	YEAR	—	PLATE	34667 — Dubai
CUSTOMER	Me george	MILEAGE	— km	VIN	—

REPORTED COMPLAINT

سحب السيارة ضعيف

OUR DIAGNOSIS

قواعد Engine mounts هيتغير الاول و هيتم تجربة السيارة قواعد المحرك oxygen sensor المشكلة في
Front تغيير فحمت الفرامل الأمامية Clutch replacement تغيير كلتش الجير بوكس Transmission mounts الجير بوكس
Brake discs دسك اسكيمي Rear brake pads replacement تغيير فحمت الفرامل الخلفية brake pads replacement
Left CV boot تغيير ربرة الأكسل اليسار Cabin air filter فلتير المكيف Engine air filter فلتير الهواء Skimming replacement

REPAIR QUOTE (AED)

ITEM	TYPE	QTY	AMOUNT (AED)
Oxygen sensor	New part	1	—
Change spark plugs	Labour	—	120
Engine mounting	Labour	—	150
Gear mounting	Labour	—	150
Change clutch	Labour	—	1200
Change oxygen sensor	Labour	—	50
Labour total			1670
TOTAL			1670

To approve this quote: simply reply **APPROVE** on WhatsApp **+971 54 582 6226** and we will start the work right away.

Used parts are tested before installation · Repairs covered by our 30-day workmanship warranty · Prices include the listed items only — any additional fault found will be quoted separately for your approval.